

**If you are using a printed copy of this procedure, and not the on-screen version, then you MUST make sure the dates at the bottom of the printed copy and the on-screen version match. The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ Training Office, Bldg. 911A.**

C-A OPERATIONS PROCEDURES MANUAL

ATTACHMENT

8.10.2.b Collider Fence Posting List

C-A-OPM Procedure in which this Attachment is used		
8.10.2		

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: \_\_\_\_\_ *Signature on File* \_\_\_\_\_  
 Collider-Accelerator Department Chairman Date

A. Etkin

## Collider Fence Posting List

Fence Location	Permanent Postings	Running Period Postings
Perimeter Fence - 1004 – 1008 and Ring Rd. 1005 Area	Caution Controlled Area Area Controlled for Radiation Protection Purposes. For Entry, You Must Have Radiological Training or Be Escorted by a Trained Individual.	
Cryo Pipes		Caution Controlled Area
Buildings 1002, 1004, 1006, 1008 and 1012 Scrapers Beam Dumps Pads – 1004, 1008, 1012	Caution Controlled Area – See gate for Entry Requirements	At Gate – Contact MCR for Entry
Security Perimeter Fence – 1008 - 1004	At Access Points – Caution Controlled Area	
Pad - 1002	Caution Controlled Area – See gate for Entry Requirements	At Gate – Contact MCR for Entry On Shield Wall – Caution No Climbing No Ladders
Injection Areas on Berm		Caution Radiation Area TLD Required
Survey Shafts	Radiation Barrier Contact Liaison Engineer Before Entry	